

# General Environmental Incident Summary

**Incident:** 3994      **Date/Time Notice:** 1/5/2016      21:00      **DEM Incident No:**  
**Responsible Party:** MBI Energy Services  
**Date Incident:** 1/5/2016      **Time Incident:** 14:00      **Duration:** 40 minutes  
**County:** McKenzie      **Twp:** 151      **Rng:** 102      **Sec:** 7      **Qtr:**  
**Lat:** 47.37993      **Long:** -103.50700      **Method:** Navigation quality GPS  
**Location Description:** West on Beicegel Road North of Grassy Butte (off of HWY 85). Travel West on Beicegel Road for approximately 22.5 miles.

**Submitted By:** Chad Miller      **Affiliation:**  
**Address:** 12980 35th St SW  
**City:** Belfield      **State:** ND      **Zip:** 58622

## Received By:

**Contact Person:** Chad Miller  
12980 35th St SW  
Belfield, ND 58622

**Distance Nearest Occupied Building:** 4 Miles      **Release Contained:** No

**Type of Incident:** Vehicle Accident

**Description of Released Contaminant:** Production Water

**Volume Spilled:** 40.00 barrels      **Ag Related:** No

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** Unknown

## Cause of Incident:

Truck hauling production water lost traction while climbing a steep hill. The truck and pup trailer slid backward, the pup broke free of tractor and rolled into ditch.

## Risk Evaluation:

None

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

Impact to soil.

## Action Taken or Planned:

Lowest line of migration was dammed. Supervac trucks were used to vacuum up standing water. Contaminated soil will be excavated.

**Wastes Disposal Location:** Contaminated material will be disposed of at permitted disposal facility.

**Agencies Involved:** USFS

## **Updates**

---

**Date:** 1/6/2016      **Status:** Inspection

**Author:** Espe, Brady

### **Updated Volume:**

#### **Notes:**

I arrived at the site at 11:00 a.m. The weather was clear and 16°F, with wind from the southeast 0-5 mph. There were company personnel at the site ready to remove the soil from the ditch. They were waiting for a company to locate the utility line. The accident occurred near the crest of a hill, and the produced water drained into the ditch, following it for approximately 600' to where the last boom was placed. There was no standing liquid in the ditch; the produced water remained in the west ditch and did not reach any drainages. The nearest culvert and drainage is near the cattle crossing north of the spill about another 600'. The facility is located on U.S. Forest Service land, and that agency retains oversight. 47.38083, -103.50639

---

**Date:** 1/6/2016      **Status:** Reviewed - Follow-up Required

**Author:** O'Gorman, Brian

### **Updated Volume:**

#### **Notes:**

According to the report, 40 barrels of production water were released along Beicegel Road in McKenzie County. Location is within U.S. Forest Service property. Inspector Espe will be on location today for further followup.